

# JN CHEVROLET

## PROJECT PROFILE

---



**Client:** JN Chevrolet

**Location:** 2780 Waiwai Loop, Honolulu, HI 96819

**Project Duration:** January 2025 – March 2025

**Project Manager:** Jason Simms

**Contractor:** R & C Roofing

### Scope & Systems

- **Removal:** Existing coating in upper deck area
- **Replacement:** 10-Year liquid-applied vehicular system
- **Ramp Area:** Recoat of existing coating
- **AVM Systems Used:**
  - AVM Epoxy Primer 401 FC
  - AVM System 620V

### Construction Process Overview

- Extensive crack chasing and surface preparation
- Significant concrete repairs
- Structural reinforcement
- Application of primer and vehicular coating system

### Challenges & Solutions

- **Challenge:** Severely damaged and deteriorated deck — “the worst deck I have ever seen”
- **Challenge:** Multiple contractors and manufacturers refused to take on the project
- **Solution:** AVM and R & C Roofing stepped in with a strategic repair plan and durable AVM products, delivering a solution where others wouldn’t

### Results

- Successfully restored a heavily deteriorated vehicular deck
  - Installed a robust, long-lasting 10-Year AVM System 620V solution
-

# JN CHEVROLET

## PROJECT PROFILE

